

## Switch Preparation




Illustration 1: Attach wires to center and post farthest away from actuator (switch shown in SMT Designs Wiring Assistant)




Illustration 2: Solder Wires



## **Switch Preparation**



Illustration 3: Slide small section of heatshrink tubing over posts



Illustration 4: Shrink tubing